

# Vehicle Diagnostic Report

The Report is created by **LAUNCH X-431**

## Vehicle Information



Year:2013  
 Make:Peugeot  
 Model:508  
 VIN:VF38DRHC8DL005651  
 Odometer:269235 km  
 Vehicle Software Version:V44.17  
 Diagnostic Application Version:V8.00.039  
 Diagnostic path: > 508 > Health Report

## Repair Shop

Shop Name:  
 Address:  
 Zip Code:  
 Telephone:  
 Email:  
 SN:987940059993  
 Test Time:2026-06-04 16:39:33



## System fault code 【Pre-Repair】

The following systems is abnormal:

### Built-In Systems Interface(Bsi)

#### DTC (12)

|                                                                                                                   |              |
|-------------------------------------------------------------------------------------------------------------------|--------------|
| 1.B1003 Configuration Fault                                                                                       | Permanent    |
| 2.U1F00 Fault Event Not Stored In The Faults Log                                                                  | Permanent    |
| 3.B180E Fault In Authenticating The Hands-free Remote Control Not Present In The Reader                           | Intermittent |
| 4.B173D Fault In Identifying The Mechanical/Electronic Key Or The Hands-free Remote Control Present In The Reader | Intermittent |
| 5.B1163 Number Plate Lighting Control Fault                                                                       | Permanent    |
| 6.B1715 Lack Of Coherence Between The Vehicle Locking Status And The Locking Status Of The Front Right Door Lock  | Intermittent |
| 7.B171C Front Right Lock Status Fault (Lock Closed But Declared Open)                                             | Intermittent |
| 8.B1818 Oil Level Fault                                                                                           | Intermittent |
| 9.U1809 Oil Temperature Information Fault                                                                         | Intermittent |
| 10.B132A Air Conditioning Circuit Low Pressure Safety Fault                                                       | Permanent    |

|                                                           |              |
|-----------------------------------------------------------|--------------|
| 11.B132F Air Conditioning High Pressure Information Fault | Intermittent |
| 12.U1F2E No Communication With Engine ECU                 | Intermittent |

#### Engine Wiring Housing

|                                   |           |
|-----------------------------------|-----------|
| DTC (2)                           |           |
| 1.B113A Left-hand Main Beam Fault | Temporary |
| 2.B1139 Fault RH Main Beam        | Present   |

#### Hands Free Kit

|                                                                 |           |
|-----------------------------------------------------------------|-----------|
| DTC (1)                                                         |           |
| 1.B1724 Accesses Unlocking Sensor Fault (Front Right-hand Door) | Temporary |

#### Services Module

|                                  |  |
|----------------------------------|--|
| DTC (1)                          |  |
| 1.0D80 GSM Module Internal Fault |  |

#### Matrix Screen Integral To The Instrument Panel

|                                            |           |
|--------------------------------------------|-----------|
| DTC (1)                                    |           |
| 1.U1803 Engine Oil Level Information Fault | Temporary |

#### Switch Module Under The Steering Wheel (Top Of Column)

|                                  |           |
|----------------------------------|-----------|
| DTC (1)                          |           |
| 1.B1836 Transponder Aerial Fault | Permanent |

#### Main Beams Assistant ECU

|                                     |           |
|-------------------------------------|-----------|
| DTC (3)                             |           |
| 1.U1802 Vehicle Speed Data Fault    | Temporary |
| 2.B100D Operating Temperature Fault | Temporary |
| 3.B100E Operating Temperature Fault | Temporary |

#### Telematics Unit(Rtx) Or Radio Navigation

|                                                                  |       |
|------------------------------------------------------------------|-------|
| DTC (1)                                                          |       |
| 1.0303 Configuration Fault (Redo The Configuration) :: No Signal | Local |

The following systems are OK:

- 1.Engine ECU
- 2Automatic Gearbox
- 3.Anti-Lock Braking System (ABS) Or Electric Stability Program (ESP)
- 4.Air Bags
- 5.Instrument Panel
- 6.Air Conditioning
- 7.Battery Charge Status Unit
- 8.Power Steering GEP
- 9.Parking Assistance
- 10.Supply Protection And Management Unit

- 11.Rain/ Brightness Sensor
- 12.Headlamp Height Adjuster/Directional Headlamp
- 13.Steering Wheel With Integral Controls (VCI)
- 14.Audio-Navigation System/Connected Audio System Controls
- 15.Windscreen Wiper (Left-Hand Side)
- 16.Windscreen Wiper (Right-Hand Side)
- 17.Electric Key Reader
- 18.Electric Secondary Brake
- 19.Multiplexed Control Panel
- 20.Driver's Door Control Pad
- 21.Rear Air Conditioning
- 22.High Head Vision
- 23.Seat Belts Not Fastened LED Unit (TNB)

---

### Disclaimer

This test report is for reference only for vehicle test and maintenance. The vehicle operating data provided in this report are all static data. The detailed dynamic diagnostic data can be read by professional maintenance device, and LAUNCH will not be liable for any accidents and failures arising therefrom!