

Vehicle Diagnostic Report

The Report is created by **LAUNCH X-431**

Vehicle Information



Year:2006
Make:Volvo
Model:V50
VIN:YV1MW765262218713
Odometer:272316 km
Vehicle Software Version:V45.05
Diagnostic Application Version:V8.00.039
Diagnostic path: > Health Report

Repair Shop

Shop Name:
Address:
Zip Code:
Telephone:
Email:
SN:987940059993
Test Time:2026-07-07 17:38:28



System fault code 【Pre-Repair】

The following systems is abnormal:

ABS (Anti-Lock Braking System)

DTC (5)

- 1.ABS-0101 Communication Between Control Modules. Communication Problems With The Engine Control Module (ECM)
- 2.ABS-0115 Communication Between Control Modules. Communication With The Steering Wheel Module (SWM). Signal Missing
- 3.ABS-0100 Communication Between Control Modules. Communication Problems With The Engine Control Module (ECM)
- 4.ABS-E003 Control Module. Faulty Configuration
- 5.ABS-0097 Communication Between Control Modules. Communication Problems With The Central Electronic Module (CEM)

DIESEL ENG (Fuel System/Combined System)

DTC (9)

- 1.ECM-136F Mass Air Flow (MAF) Sensor. Signal Too Low
- 2.ECM-9530 Accelerator Position Sensor.

- 3.ECM-928C Cruise Control. Faulty Signal
- 4.ECM-E010 Configuration Problem. Software Error
- 5.ECM-580F Engine Control Module (ECM).
- 6.ECM-A600 Additive Dosage Module (ADM). Faulty Signal
- 7.ECM-6720 EGR Regulation. Flow Too High
- 8.ECM-1600 Charge Pressure Sensor.
- 9.ECM-445D Exhaust Gas Recirculation (EGR) Control. Offset Error

CEM (Central Electrical Module)

DTC (3)

- 1.CEM-4F33 Battery Temperature Faulty Signal
- 2.CEM-DE11 Communication With ECM Control Module. Signal Missing
- 3.CEM-DE45 Communication With The Passenger Door Module (PDM). Signal Missing

ICM (Infotainment Control Module)

DTC (3)

- 1.ICM-1A03 Control Module. Faulty Voltage
- 2.ICM-1F36 Heating, Display. Signal Missing
- 3.ICM-1A5A Control Module. No Signal

EPS (Electronic Power Steering)

DTC (3)

- 1.EPS-E003 Configuration Fault. Faulty Configuration
- 2.EPS-0080 Steering Wheel Angle Sensor. Faulty Signal
- 3.EPS-0082 Engine Status. Faulty Signal

The following systems are OK:

- 1.SRS (Supplemental Inflatable Restraint System)
- 2.DIM (Driver Information Module)
- 3.DDM (Driver Door Module)
- 4.CCM (Climate Control Module)
- 5.SWM (Steering Wheel Module)
- 6.IAM (Integrated Audio Module)

Disclaimer

This test report is for reference only for vehicle test and maintenance. The vehicle operating data provided in this report are all static data. The detailed dynamic diagnostic data can be read by professional maintenance device, and LAUNCH will not be liable for any accidents and failures arising therefrom!